

MATERIAL SAFETY DATA SHEET  
COPYRIGHT GENERAL ELECTRIC CO.

PAGE:  
SS4004

6

PRODUCTS/INGREDIENTS

THIS SPACE RESERVED FOR SPECIAL USE.

PREVENTATIVE MEASURES (SECTIONS VII, VIII, IX)

\*\*\* VII SPECIAL PROTECTIVE EQUIPMENT \*\*\*

RESPIRATORY PROTECTION:

USE IN A WELL VENTILATED AREA.

USE APPROVED NIOSH RESPIRATORY PROTECTION IF TLV EXCEEDED.....  
OR OVER EXPOSURE IS LIKELY.

PROTECTIVE GLOVES:

RUBBER GLOVES.

EYE AND FACE PROTECTION:

SAFETY GLASSES.

MONOGOGGLES.

OTHER PROTECTIVE EQUIPMENT:

WEAR EYE PROTECTION AND PROTECTIVE CLOTHING.

VENTILATION:

USE ONLY IN WELL VENTILATED AREA.  
MECHANICAL VENTILATION.

\*\*\* VIII SPILL, LEAK AND DISPOSAL PROCEDURES \*\*\*

ACTION TO BE TAKEN IF MATERIAL IS RELEASED OR SPILLED:

WIPE, SCRAPE OR SOAK UP IN AN INERT MATERIAL AND PUT IN A  
CONTAINER FOR DISPOSAL.

WEAR PROPER PROTECTIVE EQUIPMENT AS SPECIFIED IN THE PROTECTIVE  
EQUIPMENT SECTION.

REMOVE SOURCES OF IGNITION.

WARN OTHER WORKERS OF SPILL.

INCREASE AREA VENTILATION.

DISPOSAL METHOD:

DISPOSAL SHOULD BE MADE IN ACCORDANCE WITH FEDERAL, STATE AND  
LOCAL REGULATIONS.

\*\*\* IX SPECIAL PRECAUTIONS \*\*\*

PRECAUTIONS TO BE TAKEN IN HANDLING AND STORAGE:

USE GROUND STRAP.

STORE UPRIGHT IN A COOL PLACE BELOW 30'C (85'F).

KEEP CONTAINER CLOSED WHEN NOT IN USE.

AVOID BREATHING VAPORS, IF EXPOSED TO HIGH VAPOR CONCENTRATION,  
LEAVE AREA AT ONCE.

AVOID CONTACT WITH SKIN AND EYES.

USE ONLY IN A WELL VENTILATED AREA.

DO NOT INHALE VAPORS.

DANGER! EXTREMELY FLAMMABLE.

EMPTIED CONTAINERS MAY RETAIN HAZARDOUS PROPERTIES. DO NOT CUT,  
PUNCTURE OR WELD ON OR NEAR THE CONTAINER.